

VEHICLE INSPECTION REPORT

PF20ACO

Mercedes-Benz Sprinter 314 CDI

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 31/07/2020

Year 2020

Mileage 140,979 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN W1V9076352P255553

Body Style Panel Van L3

MOT Due 25/03/2027

CAP Clean £8,625.00

CAP Average £7,575.00

CAP Below £6,050.00

Gearbox AUTOMATIC

Gears 6

AD BLUE, SIDE LOADING DOOR

Tyres

NSF

NSR

OSF

OSR




Spare

Features


- Rear parking sensor
- Front electric windows

Photos





Condition Check



Damage Photos



1: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



2: Wing osf
Scratched
Over 25mm Thru Paint



3: Bonnet
Chipped
Multiple Chips

4: Screen Front
Chipped
UpTo 10mm



5: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm

6: Wing nsf
Dented
With Paint Damage



7: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm

8: Door nsf
Scratched
Over 25mm Not Thru Paint



9: Door nsf
Dented
Over 30mm

10: B Post ns
Dented
With Paint Damage



11: Door nsr
Dented
With Paint Damage

12: Door nsr
Dented
Over 30mm



13: Door nsr
Scratched
Over 25mm Thru Paint

14: Qtr Panel nsr
Dented
With Paint Damage




15: Sill ns
Dented
With Paint Damage

16: Qtr Panel nsr
Dented
With Paint Damage



17: Sill ns
Dented
With Paint Damage

18: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



19: Bumper Rear Moulding
Missing
Replace

20: Qtr Panel nsr
Dented
With Paint Damage




21: Door nsr
Dented
Over 30mm

22: Roof
Dented
Over 30mm



23: Door nsr
Dented
With Paint Damage

24: Badgedecal Rear
Missing
Replace



25: Door osr
Dented
With Paint Damage

26: Qtr Panel osr
Dented
With Paint Damage



27: Qtr Panel osr
 Scratched
 Over 25mm Not Thru Paint

28: Qtr Panel osr
 Dented
 With Paint Damage



29: Qtr Panel osr
 Scratched
 Over 25mm Thru Paint

30: Qtr Panel osr
 Dented
 With Paint Damage



31: Qtr Panel osr
 Dented
 With Paint Damage

32: Carpets Front
 Holed
 Over 3mm



33: Steering Wheel
 Damaged
 Replace

Interior

Carpet Condition		Upholstery Condition	
Seat Condition	Average	Odour	Average
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK