

VEHICLE INSPECTION REPORT

BX59DGY

Daf LF 45.160

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow


Details







Reg. date	10/11/2009	VIN	XLRAE45FF0L354000	Gearbox	MANUAL
Year	2009	Body Style	Box Van	Axle Combi	4x2
Mileage	378,010 Km Warranted	Service history	Yes	Rear Suspension	Steel
Fuel Type	Diesel	MOT Due	30/06/2026	Rear Doors	Roller
Colour	WHITE	Cab Type	DAY CAB		



Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4


Photos







Condition Check



Damage Photos



1: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



2: Wing osf
Scratched
Over 25mm Not Thru Paint



3: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm

4: Bonnet
Chipped
Multiple Chips



5: Grille Front
Broken
Replace

6: Grille Front
Broken
Replace



7: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm

8: Wing nsf
Scratched
Over 25mm Thru Paint



9: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm

10: Other
N/A
N/A



11: Panel Rear
Scratched
Over 25mm Thru Paint

12: Door nsr
Dented
Over 30mm



13: Panel Rear
Scratched
Over 25mm Thru Paint

14: Other
N/A
N/A



15: Door osf
 Scratched
 Over 25mm Not Thru Paint

Interior

Carpet Condition		Average		Upholstery Condition		Average	
Seat Condition		Average		Odour		-	
Engine Runs		OK		Gearbox 1st and Reverse Test		OK	
Brakes		OK		Clutch Slip Test from Static		OK	
Parking Brake		OK		Gearbox Static Gear Selection (engine running)		OK	
				No Excessive Smoking		OK	
EML light illuminated		OK		Oil warning light illuminated		OK	
Airbag light illuminated		OK		DPF light illuminated		Fault	
ABS light illuminated		OK		Service indicator light illuminated		OK	